



HEIGHT SAFETY INSPECTION REPORT



Inspection No. 2292

Client

DeMartini Fletcher Property
Level 10, 46 Edward Street Brisbane QLD 4000

Site No. 2519
The Lakes Centre - Block A - 8-22 King Street, Caboolture

Client Contact
Clare Burton
0732112033
Maintenance@demartini.com.au



Reviewed By: Damien Hewitt (Supervisor)
Damien/supervisor

Safe@Heights Height Safety Specialists

18 Rowland St, Slacks Creek QLD 4127 Phone: 07 3208 5833 sales@safeatheights.com.au www.safeatheights.com.au



THE LEADERS IN HIGH QUALITY QUEENSLAND MADE HEIGHT SAFETY ACCESS AND FALL PREVENTION SYSTEMS







Table of Contents

Disclaimer	p. 3
The Complete Solution	p. 4
Proudly Queensland	
Inspection Scope	p. 6
Roof Plan	p. 7
MAIN ROOF - Item #1: Observation	p. 10





DISCLAIMER

This Height Safety Report has been produced by Safe @ Heights Pty Ltd. It specifies the type/s and numbers of the height safety systems installed on this building. Only qualified and competent persons should use a height safety system and only after they have been authorised to do so by the system owner. All users must have undergone the correct training and be deemed competent to use the system/s.

A detailed Safe Work Method Statement (SWMS) must be completed prior to using any height safety system. A rescue plan must accompany all SWMS when using a fall arrest system. It is the responsibility of the owner of this system to ensure the following BEFORE the system can be safely used as per below:

- The design is fit for purpose
- There is an induction available that clearly explains how to use the system/s safely and that all works undergo this prior to using the system/s
- The user/s has the required training, experience and PPE to use the system safely
- All workers comply with current safety procedures as stated in the current Codes of Practice and Australian Standards for working at heights
- Use of a Full Body Harness with Energy Absorber complying with AS/NZ 1891.1 must be used when connected to any fall arrest system

Safe @ Heights Pty Ltd does not take any responsibility for or are liable for any injury or death caused by incorrectly using this system/a or any other system which has been installed or certified by Safe @ Heights Pty Ltd. Safe @ Heights Pty Ltd expressly prohibits the illegal use of this document. This document should be used as a guide only in the creation and planning of a specific SWMS and rescue plan by all users. Report is to be used exclusively for the purpose it was designed for, and is not to be copied, reproduced or distributed in any way in part or wholly without permission of Safe @ Heights Pty Ltd

Height Safety is everyone's responsibility.

DO NOT USE THIS SYSTEM/S IF YOU DO NOT FEEL COMPETENT TO USE THE SYSTEM CORRECTLY AND SAFELY.







THE COMPLETE SOLUTION

Who we are

Safe@Heights specialise in fall prevention, fall arrest and height access solutions. Whether your requirement is as simple as a ladder bracket to access a roof, a complete building solution or a state wide project, we can help. Our projects range in size from \$1000 to over \$500,000. As a Queensland based manufacturer and installer there is nothing we can't do.

The benefits of dealing directly with the manufacturer who also completes the installations are;

- High quality Queensland made products
- Custom solutions specifically designed for your site
- Specialist knowledge that only comes from thousands of hours of designing and testing height safety systems
- Longer Product and Installation Warranties
- Installation by highly trained trade qualified installers
- Your own dedicated Project Manager
- Access to OH&S specialists
- Peace of mind that you have the right solution for you









PROUDLY QUEENSLAND



OLD MADE

As the manufacturer and installer there is nothing we can't do. Over 95% of our systems have been proudly designed, engineered and manufactured right here in Queensland. Safe@Heights specialises in fall prevention, fall arrest and access solutions. Regardless of your requirements we are able to help you. Whether it is as simple as a ladder bracket to access a roof, a complete building solution or a state wide project, we can help. Our projects range in size from \$1000 to over \$500,000. As the manufacturer we are able to provide customised solutions that suit your unique requirements and budget.

TRADE QUALIFIED

Our installers are all trade qualified and extensively trained in height safety system installation. We do not use subcontractors. All installations, servicing, inspections and certifications are completed by our own dedicated team. They know our products inside and out. Compliance and safety is guaranteed. Our team of installers are proud of our Queensland Made Systems and take the utmost care and attention with our installations. Close enough is never good enough for our team. They are perfectionists who love what they do.

INSPECTIONS & AUDITS

All height safety access, fall prevention and fall arrest systems must be inspected and certified as compliant and safe on a regular basis. This is not only to ensure you are complying with your legal duties under the Work Health and Safety Act and Australian Standards, but more importantly to ensure that your systems are safe to use and remain fit for purpose

To assist you with this, we have our Certification & Safety Program. We take all the hassle and worry out of inspecting, certifying and maintaining your systems. Members enjoy a number of benefits such as our industry leading 15 Year Warranty*, automatic inspection scheduling and free access to our HawkPro Compliance Management System.

For more information about becoming a member please contact our team at any time on (07) 3208

QUALITY ASSURANCE

All of our installations come with a standard 5 Year Product and Installation Warranty. Members of our Certification & Safety Program automatically get upgraded to our Industry Leading 15 Year Warranty on all of our HawkPro systems. For any non HawkPro systems, the manufacturers product warranty will apply. However, the installation warranty is extended to 15 Years. Please refer to our warranty policy for full terms and conditions.







HEIGHT SAFETY INSPECTION REPORT

Inspection - The Lakes Centre - Block A - 8-22 King Street, Caboolture - Block A

Safe@Heights has completed an inspection of the above address.

Please see below a summary of the systems inspected, followed by individual system certificates and full audit report. Where an item has failed or an issue has been identified, it will be highlighted red. Please take the time to review the report in full, including any of our recommendations. If you have any questions, please do not hesitate to contact us at any time.

Your next inspection due date is listed in the below table. We will be in contact with you approximately 6 weeks prior to this date to arrange the next service.

Thank you for partnering with Safe@Heights to maintain your height safety system compliance. If we can be of further service please do not hesitate to contact us.

Summary Table

Job#	2292	
Site Contact	Kai Kapusta - 0435 947 675	
Date of Inspection	22/04/2025	
Date of Next Inspection	22/04/2026	
Certified By	Damien Hewitt (Supervisor), Aaron Parr	

Height Safety Systems Summary Table

System Type	Quantity
-------------	----------

Failed Items and Recommendations

System Type	Item Status	Recommendation
MAIN ROOF - Item #1 - Observation - OBS1 - No Height Safety Systems Installed	High Risk - Identified hazard	Warning: There is NO safe access onto this roof, no height safety systems have been installed.

QBCC 1245777







Roof Plan

Plan View



Northern Elevation



ADDRESS 18 ROWLAND ST, SLACKS CREEK QLD 4127 © SAFE @ HEIGHTS PTY LTD 2022








Western Elevation










Proposed part install







MAIN ROOF - Item #1: Observation

Identification #	OBS1 - No Height Safety Systems Installed	
Date of Observation	01/07/2025	
1 Name of Observation		
No Height Safety Systems Installed		
2 Take a photo of the observation		




















3 Describe the issue with as much detail as required		
Review quote #11963 for details		
Observation Status:	High Risk - Identified hazard	
Recommendations:	Warning: There is NO safe access onto this roof, no height safety systems have been installed.	

